

Impact 12.2.5 - Release Notes

Welcome to Impact, a complete range of software and hardware to solve your machine vision needs. Impact is the most complete product line with the same software used throughout. Impact reduces your cost of ownership and provides you with the flexibility that today's quickly changing manufacturing environment requires.

These Release Notes describe enhancements in this software release, along with known bugs that were fixed. Refer to the Readme file for more information about this software release. significant

Check our website at www.datalogic.com/ for any newer releases, information on other Impact software and hardware products, and technical support.

This document is divided into the following sections:

[Enhancements in this release](#)

[Bugs Fixed in this release](#)

[Readme Documentation](#)

Enhancements in this release

- MC Protocol update to reduce the overhead of the tools MC Read / MC Write.
- Apply Calibration Processing time speed-up for P-Series.
- Image List add element speed up.

Bugs fixed in this release

- [Fixed] Uncaught exception when highlight and enter a new name using Korean language.
- [Fixed] VisionSDK solved an error that prevent discovery of P1x Cameras.
- [Fixed] Incorrect Syslog entry created by the Origin tool.
- [Fixed] Camera Settings Unexpected Change on MX-E-90 when Cam 6 disconnected.
- [Fixed] Solved an error for Pattern Find that prevent adding a region of interest if removed.
- [Fixed] Solved an error for Advanced OCR Control in CPM that freeze CPM after pressing the Train button.
- [Fixed] Solved an error that prevent E181 connection to MX-E20 after warm boot

Readme Documentation

More information can be found in *readme.pdf* file in documentation folder inside VPM installation.